

SECTION 2 SURVEY REPORT

SURVEY SITE	COURT GATE	SURVEYOR	D W Barron
SURVEY DATE	25-26/05/06		



Reference Number	Building Identifier	Room Identifier	Extent / Area	Level Of Identification	Accessibility / Vulnerability	Product Type	Product Score	Damage/Deterioration	Surface Treatment	Asbestos Type	Material Algorithm Score	Risk Level	Surveyors Recommendation	Photograph Reference
Title-Cottage														
✓ TTC-CGCOT-1	Ground floor	External w.c.	Item	Presumed	Occasionally disturbed	w.c. seat	1	0	0	1	2	Very low	Management by labelling/registering/periodic inspection	Title-Cottage TTC-CGCOT-1
✓ TTC-CGCOT-1	Ground floor	External w.c.	Item	Presumed	Usually inaccessible/unlikely disturbance	w.c. cistern	1	0	0	1	2	Very low	Management by labelling/registering/periodic inspection	TTC-CGCOT-1A
✓ TTC-CGCOT-2	First floor	Internal w.c.	Item	Presumed	Occasionally disturbed	w.c. seat	1	0	0	1	2	Very low	Management by labelling/registering/periodic inspection	TTC-CGCOT-2
Title-Library														
Title-Jenni Lee														
✓ TTC-CGJL-1	Ground floor	Reception	Item	Presumed	Usually inaccessible/unlikely disturbance	Sink pad	1	0	0	1	2	Very low	Management by labelling/registering/periodic inspection	Title-Library TTC-CGJL-1
✓ TTC-CGJL-1	Ground floor	Reception		Presumed	Usually inaccessible/unlikely disturbance	Draining board pad	1	0	0	1	2	Very low	Management by labelling/registering/periodic inspection	TTC-CGJL-1A
Title-Museum														
✓ TTC-CGMU-1	Ground floor	Store	Apx.4m2	Identified	Easily disturbed- wall lining	Asbestos insulating board	2	0	2	2	6	Low	Management by labelling/registering/periodic inspection	Title-Museum TTC-CGMU-1
✓ TTC-CGMU-1	Ground floor	Store	Apx.4m2	Strongly presumed	Occasionally disturbed- stair underlining	Asbestos insulating board	2	0	1	2	5	Low	Management by labelling/registering/periodic inspection	None
✓ TTC-CGMU-2	Ground floor	Staircase	Apx.35 lin m.	Presumed	Easily disturbed	Stair nosings	1	0	0	1	2	Very low	Management by labelling/registering/periodic inspection	TTC-CGMU-2
✓ TTC-CGMU-3	First floor	Old Masonic room	Apx.3 lin m.	Presumed	Easily disturbed	Stair nosings	1	0	0	1	2	Very low	Management by labelling/registering/periodic inspection	TTC-CGMU-3
✓ TTC-CGMU-3	First floor	Old Masonic room	Apx.3 lin m.	Presumed	Easily disturbed	Stair nosings	1	0	0	1	2	Very low	Management by labelling/registering/periodic inspection	TTC-CGMU-3A
✓ TTC-CGMU-4	First floor	Reception	Apx.50m2	Presumed	Usually inaccessible/unlikely disturbance	Roofers felt	1	1	0	1	3	Very low	Management by labelling/registering/periodic inspection	TTC-CGMU-4